

ORDER NO SO0057895	DATE 05/31/2024
------------------------------	--------------------

TITAN MACHINERY-SCOTTSBLUFF
PO BOX 1070
SCOTTSBLUFF NE 69363-1070

CUSTOMER NO BP0015631	PAGE NO 1
--------------------------	--------------

PAYMENT TERMS Credit Card

**SERVICE INVOICE
(PROFORMA)**

CUSTOMER PO Uptime Inspection.

INVOICE TO:

WORK SITE:

ZEILER, MIKE
110293 COUNTY RD 33
MINATARE NE 69356-1929

TITAN MACHINERY-SCOTTSBLUFF
PO BOX 1070
SCOTTSBLUFF NE 69363-1070

SALESMAN: GIECK, SETH
CONTACT :

SERVICE ORDER : SO0057895
REF:

CASE IH MODEL:340 TRACT2 S/N: ZERF05987 CUST UNIT: UNIT:E00037785
METER : 2495

SEGMENT : 1 Uptime Inspection UPTIME INSPECTION CHARGE

SEGMENT TYPE: Chargeable

CASE IH MODEL:340 TRACT2 S/N:ZERF05987 CUST UNIT: UNIT:E00037785

Worksite : TITAN MACHINERY-SCOTTSBLUFF PO BOX 1070 SCOTTSBLUFF NE 69363-1070

METER : 2643

CORRECTION:

Preform uptime inspection, remove outside duals and slide out tires and
check over for oil leaks

ITEM Lot ID	DESCRIPTION	QTY	B/O	PRICE(USD)CORE	TOTAL
	UPTIME INSPECTION	0.00		0.00	
SEGMENT	1 TOTAL:				
	0.00 PARTS	0.00 Labor		MISC.	0.00 TAX

SEGMENT : 2 Engine replacement AG LABOR

SEGMENT TYPE: Chargeable

CASE IH MODEL:340 TRACT2 S/N:ZERF05987 CUST UNIT: UNIT:E00037785

Worksite : TITAN MACHINERY-SCOTTSBLUFF PO BOX 1070 SCOTTSBLUFF NE 69363-1070

METER : 2495

WORK DESCRIPTION :

Engine replacement

CORRECTION:

Time not covered by PIP to replace engine block.

ITEM Lot ID	DESCRIPTION	QTY	B/O	PRICE(USD)CORE	TOTAL
73344303	OAT 50/50 ANTIFREEZE SHOP SUPPLIES	6 0.00	0	0.00	

ORDER NO
SO0057895

DATE
05/31/2024

TITAN MACHINERY-SCOTTSBLUFF
PO BOX 1070
SCOTTSBLUFF NE 69363-1070

CUSTOMER NO
BP0015631

PAGE NO
2

PAYMENT TERMS
Credit Card

SERVICE INVOICE
(PROFORMA)

CUSTOMER PO
Uptime Inspection.

ITEM Lot ID	DESCRIPTION	QTY	B/O	PRICE(USD)CORE	TOTAL
----------------	-------------	-----	-----	----------------	-------

SEGMENT 2 TOTAL:
PARTS Labor MISC. 0.00 TAX TOTAL

SEGMENT : 3 Uptime Repair UPTIME INSPECTIONS AG REPAIR
SEGMENT TYPE: Chargeable
CASE IH MODEL:340 TRACT2 S/N:ZERF05987 CUST UNIT: UNIT:E00037785
Worksite : TITAN MACHINERY-SCOTTSBLUFF PO BOX 1070 SCOTTSBLUFF NE 69363-1070
METER : 2495

WORK DESCRIPTION
Uptime Repair

CORRECTION:
Check oil on differential and planetary, replace DEF filters. Found that the three point hitch valve is leaking. Replace oring on hitch valve, remote control valve, and remove fuel tank from left side to reseal inspections cover on range housings of transmission. Reinstall rear tires and duals.

ITEM Lot ID	DESCRIPTION	QTY	B/O	PRICE(USD)CORE	TOTAL
504339903	FILTER ENGINE O	1	0	0.00	
17291881	GASKET	1	0	0.00	
504147366	GASKET	1	0	0.00	
47364243	FILTER DEF	1	0	0.00	
228273A1	BOLT	2	0	0.00	
228273A1	BOLT	2	0	0.00	
228273A1	BOLT	1	0	0.00	
MC38655	515 GASKET MAKER	1	0	0.00	
87635382	O-RING	13	0	0.00	
87635380	O-RING	6	0	0.00	
87635379	O-RING	6	0	0.00	
87635376	O-RING	2	0	0.00	
87635380	O-RING	4	0	0.00	
LP-0230		3	0	0.00	
364360C2	HOSE PER FT 3/4 ID	1	0	0.00	
9992069	O-RING	12	0	0.00	
9992298	O-RING	8	0	0.00	
228273A1	BOLT	2	0	0.00	
B134A30	134 FREON	4	0	0.00	
73344265	HY-TRAN 1 GAL	1	0	0.00	
5801659560	OIL SEPARATOR	1	0	0.00	
18190598	FASTENER	1	0	0.00	
	FREIGHT & HANDLING	0.00			
	SHOP SUPPLIES	0.00			

ORDER NO SO0057895	DATE 05/31/2024	TITAN MACHINERY-SCOTTSBLUFF PO BOX 1070 SCOTTSBLUFF NE 69363-1070		CUSTOMER NO BP0015631	PAGE NO 3
PAYMENT TERMS Credit Card		SERVICE INVOICE (PROFORMA)		CUSTOMER PO Uptime Inspection.	

ITEM Lot ID	DESCRIPTION	QTY	B/O	PRICE(USD)CORE	TOTAL
----------------	-------------	-----	-----	----------------	-------

SEGMENT 3 TOTAL:
 [REDACTED] PARTS [REDACTED] Labor [REDACTED] MISC. [REDACTED] 0.00 TAX TOTAL

SEGMENT : 4 PIP CE0121 WARRANTY AG
 SEGMENT TYPE: Non-Chargeable
 CASE IH MODEL:340 TRACT2 S/N:ZERF05987 CUST UNIT: UNIT:E00037785
 Worksite : TITAN MACHINERY-SCOTTSBLUFF PO BOX 1070 SCOTTSBLUFF NE 69363-1070
 METER : 2495

WORK DESCRIPTION
 Perfomed PIP CE0121.

CAUSE:
 Perfomed PIP CE0121.

CORRECTION:
 REMOVE engine to replace short block tear down engine and put back together with new short block and reinstall in tractor and tested. Ran and tested, heated unit to make sure no leaks when tractor was completed.

ITEM Lot ID	DESCRIPTION	QTY	B/O	PRICE(USD)CORE	TOTAL
TPAGE0118T	KIT FIP	1	0	[REDACTED] 0.01	[REDACTED]
51491235	KIT FIP	1	0	[REDACTED] 0.01	[REDACTED]
8094257R	REMAN-SHORT ENGINE	1	0	[REDACTED] 400.00	[REDACTED]
5802054076	GASKET	1	0	[REDACTED] 0.00	[REDACTED]
5802130987	GASKET	1	0	[REDACTED] 0.00	[REDACTED]
73344223	10W40 OIL 5 GALLON B	1	0	[REDACTED] 0.00	[REDACTED]
73344221	SBL 10W40 1 GAL	2	0	[REDACTED] 0.00	[REDACTED]
73344303	OAT 50/50 ANTIFREEZE	1	0	[REDACTED] 0.00	[REDACTED]
8094257C	REMAN-SHORT ENGINE	-1	0	[REDACTED] 0.00	[REDACTED]

SEGMENT 4 TOTAL:
 [REDACTED] PARTS [REDACTED] Labor [REDACTED] 0.00 MISC. [REDACTED] 0.00 TAX TOTAL

ORDER NO SO0057895	DATE 05/31/2024
------------------------------	--------------------

TITAN MACHINERY-SCOTTSBLUFF
PO BOX 1070
SCOTTSBLUFF NE 69363-1070

CUSTOMER NO BP0015631	PAGE NO 4
--------------------------	--------------

PAYMENT TERMS Credit Card

**SERVICE INVOICE
(PROFORMA)**

CUSTOMER PO Uptime Inspection.

ITEM Lot ID	DESCRIPTION	QTY	B/O	PRICE(USD)CORE	TOTAL
----------------	-------------	-----	-----	----------------	-------

SALES TAX DETAILS:
VERTEX-VERTEX TAX

: 0.00

PARTS	
LABOR	
MISC.	
SALES TAX	
INVOICE TOTAL	(USD)

Note: